

NSMBA TAP Trail Assessment/Work Plan

Trail Maintainer: Sean Gerke
Trail: Boogie Man
Proposed Date to complete below work: TBD



Describe Problem:

The two original sections for this feature remaining are in need of replacement. The stringers are rotting and rungs are too small and the section is partly supported with one end of the support being nailed into the tree on the left.

Solution: Replace sections with a freestanding structure with bigger stringers and thicker rungs from cedar on site.

Tools/Supplies Required: hammers, nails (6" & 10"), shovels, Mattock, and cedar from on site.

Supplies requested from Landowner: Box of 6 inch spiral galvanized nails, medium sized Box of 10 inch spiral galvanized nails, and small box of 12 inch spiral galvanized nails.

NSMBA TAP Trail Assessment/Work Plan

Trail Maintainer: Sean Gerke

Trail: Boogie Man

Proposed Date to complete below work: TBD



Describe Problem:

The ride around is tight, with deadfall right beside the rider. The roots are getting more exposed and would benefit from protection.

Solution:

Cut out deadfall

Either rock armour corner or build ladder bridge corner.

Tools/Supplies Required:

Mattock, shovels, hammer and nails (6" & 10")

Supplies requested from Landowner:

NSMBA TAP Trail Assessment/Work Plan

Trail Maintainer: Sean Gerke
Trail: Boogie Man
Proposed Date to complete below work: TBD

(Enter picture of problem area here)



Describe Problem: Stringer supports are rotten and too small. In addition rungs are too small or missing.

Solution: Replace with bigger stringers and rungs from cedar on site.

Tools/Supplies Required:
Hammers, nails (6" & 10"), shovels and Mattock.

Supplies requested from Landowner: NONE

NSMBA TAP Trail Assessment/Work Plan

Trail Maintainer: Sean Gerke
Trail: Boogie Man
Proposed Date to complete below work: TBD



Describe Problem: Stringers are rotting and rungs are too small. Rungs offer poor traction because they are treated wood.

Solution: Replace bridge with better support, bigger rungs from cedar on site.

Tools/Supplies Required: Hammers, wedges, axes, and Nails (6" & 10")
Supplies requested from Landowner: NONE

NSMBA TAP Trail Assessment/Work Plan

Trail Maintainer: Sean Gerke
Trail: Boogie Man
Proposed Date to complete below work: TBD



Describe Problem: Stringers are broken and bridge has been moved to side of trail.

Solution: Replace bridge on original line to the left of where the bridge sits in the picture above. Cedar found on site.

Tools/Supplies Required: Hammers, Mattocks, Nails (6", 10")

Supplies requested from Landowner: NONE

NSMBA TAP Trail Assessment/Work Plan

Trail Maintainer: Sean Gerke
Trail: Boogie Man
Proposed Date to complete below work: TBD



Describe Problem: The ground level has eroded away by about 2 feet over time.

Solution: Build a crib and rock armour

Tools/Supplies Required: Mattock, shovels, Hammers, Nails (10" & 12") and two buckets

Supplies requested from Landowner: NONE

NSMBA TAP Trail Assessment/Work Plan

Trail Maintainer: Sean Gerke
Trail: Boogie Man
Proposed Date to complete below work: TBD



Describe Problem: Stringers on the original section of the pile driver are in need of replacement as well as some of the support posts

Solution: Install new Stringers, rungs & support post. From cedar found on site.

Tools/Supplies Required: Shovels , Mattock, Hammer, Nails (6" & 10")

Supplies requested from Landowner: NONE