

Frome Mountain

Crinkum Cankum trail repair & bypass proposal

Author: Peter Morin

This document contains a photographic walkthrough of proposed work to trail.

Objectives:

- General trail repair and maintenance.
- Reduce overall trail difficulty to intermediate level
- Create bypass to avoid 2 ladder bridges that can be extremely difficult when wet.



Armor from the ladder bridge to smooth the landing (from center of photo to bottom center).




Smooth out this section.



Starting point of bypass. Bypass will head straight through trees (center of photo).



Sequence of photos shows bypass route



Cleaning up section.




This corner will redone so it's smoother and not as steep.



This drop will be filled in.



Section cleaned up, and roots covered.



Cleaned up



This corner will be raised at the bottom and slightly banked, with the roots covered.



Cleaned up.



Cleaned up.



Smoothened out and cleaned up. This is the end of the proposed trail work.